

# Photograph 1 Mechanical Vegetation Clearance



Photograph 2 Mechanical Vegetation Clearance



Photograph 3 Manual Vegetation Clearance



Photograph 4 Manual Vegetation Clearance



## Photograph 5 Debris Removal



Photograph 6 Debris Removal



Photograph 7 Helicopter Drip Torching



Photograph 8 Helicopter Drip Torching



## Photograph 9 Helicopter Dropping Water



Photograph 10 MRS-16 Flames and Smoke



Photograph 11 Mechanical Vegetation Clearance after Burn



Photograph 12 Mechanical Vegetation Clearance after Burn



Photograph 13 Excavator at Pit



Photograph 14
Excavator Placing Spoils on Screen



Photograph 15 Expended Rocket Bodies in Pit



Photograph 16 Backhoe Completing Trench



## Photograph 17 Additional Trenching



Photograph 18 Rocket Motor from Trench



Photograph 19 Machine Gun Body from Trench



Photograph 20 EM61 Towed Array



Photograph 21 Single EM61 Unit



Photograph 22 37mm LE (UXO)



Photograph 23 M6 2.36 in HEAT Rocket (UXO)



Photograph 24 3 M6 2.36 in HEAT Rockets (UXO)



Photograph 25 M1 AT Practice Mine (UXO)



Photograph 26 M49 Surface Trip Flare (UXO)



Photograph 27 M9 Series AT Rifle Grenade (UXO)



Photograph 28 37mm HE Projectile (UXO)



Photograph 29 MKI 75mm Shrapnel Projectile (UXO)



Photograph 30 M1 AT Practice Mine Fuze (UXO)



## Photograph 31 Unfired 3 in Stokes Mortar (DMM)



Photograph 32 8 M205 Series Hand Grenade Fuzes (DMM)



Photograph 33 M159 White Star Cluster Illumination Round (DMM)

